

Periodic Inspection

Inspection Date: 01/10/2020

Property: Castle Rock, CO 80109
Tenant:



Furnace, A/C & Filter















Test Carbon Monoxide Detector(s) if within reach

















Fire Extinguisher Under Kitchen Sink (Take Photo)



Garage






Hot Water Heater







Manufactured in June 2008 which puts this unit at almost 12 years old. Water heaters have an expected life of 10-12 years. It is highly advisable to replace this one now or in the very near future and not wait for it to go out. When they go out, they typically leak. Since this unit is located upstairs, a leak has the potential to go through the floor and cave in the sheetrock in the ceiling below as well as damage the upstairs hallway carpet. Average cost to replace is \$1,400-1,500 installed by a licensed plumber.











Miscellaneous

Miscellaneous

~

Overall Condition

Overall Condition (Take Photo of Front)

Home is immaculate inside. Really sad these tenants are leaving soon as they are excellent. No issues whatsoever observed.

